

**MINISTRY OF ENERGY, MINES AND PETROLEUM RESOURCES**

**MT. POLLEY MINE**

**N. ROSE GEOTECHNICAL INSPECTION OF OPEN PIT,**

**WASTE DUMPS AND TAILINGS DAMS**

**AUGUST 30, 2006**

**FIELD NOTES AND PHOTOS**

**MP00028**

**PROJECT 2715**

**AUGUST 2006**

## GEOTECHNICAL INSPECTION OF MOUNT POLLEY MINE - AUGUST 29, 2006

Conducted by: Nick Rose, P.Eng. – Piteau Associates Engineering Ltd. (Contract to MEMPR)  
Accompanied by: Bruce Milligan – MEMPR Prince George District Health and Safety Inspector

### Pre-Inspection Meeting

Prior to the inspection, general discussions were held with Tim Fisch (General Manager) and Art Frye (Mine Operations Manager) to discuss the status of the mine plan, TSF and areas of instability. An updated operation, maintenance and surveillance (OMS) manual was provided by Ron Martel, dated August 28, 2006. The manual includes the updated management names for Mount Polley. A Golder draft technical memorandum entitled "Bell Pit – West and East Instabilities," dated August 29, 2006 was provided. The memorandum included remedial design recommendations from Golder for Bell Pit.

### Meeting with Art Frye (11:45 am – between inspection of TSF and pits/dumps)

- Discussed design for Wight Pit till slopes – southeast 2:1 or reinforced wall (design still being contemplated). Looking at possibly going closer than 40m to Bootjack Lake.
- Four wells from 15 to 30 hp (too big). Pumps to be swapped between wells based on flow.
- Bell Pit:
  - Crack on west wall; 45° fault; prisms placed on slope.
  - Toppling instability on east wall; remedial design to require stepout such that 42° from crest to crest of stepout. Interramp design was 51° - now at 44°; prisms being monitored on slope.

### Inspection Notes Corresponding to Station Locations Shown on attached Figs. 1 to 4

*Station 1:* Mill Site sump – erosion on outlet spillway. Requires remediation (e.g., rip rap).

*Station 2:* Photo of TSF from road leading to barge. Notice beaches developed since last visit.

*Station 3:* Photo from corner of Perimeter and Main embankments; notice good beach development. Filter at 947m and till core at 948.2m el. Bruce Milligan informed Ron Martel that signage is required for single lane haulage.

*Station 4:* Inclinator #3 near toe of Main Embankment; newly installed to 41m depth; pinned to bedrock. Photo of main seepage pond and downstream toe of Main Embankment.

- Seepage waters monitored weekly.
- KP lightened up on inclinometer reading frequency; were using poor-boy probes; permit requires inclinometer probe during construction.
- MPMC having difficulty acquiring probe – don't want to buy for use once per year.
- Met KP representative Jim McDonald – Les Galbraith was on site mid July; Ken Brower was on site in mid-May.
- Met Mathew Silbernagel – project coordinator for MPMC.
- No indicated issues with material specifications or borrow sources.

*Station 5:* Photo from Perimeter Embankment. Berm was placed along low point leading to South Embankment to raise the tailings pipeline such that a low point was prevented from forming in the tailings line. This has resulted in the ability to spigot across the full length of the impoundment. Spigotting was active along the South embankment to increase the beach widths in this area.

*Station 6:* Steel pipe and perforated pipe stockpiled. Steel pipe will be encased in concrete in the Perimeter Embankment to collect seepage flows from the upstream toe drains.



- Station 7:* Tension crack on west wall of Bell Pit. Maximum aperture 15cm, but generally 3 to 4 cm wide (see Fig. 2 plan map for estimated location). Continue to monitor prisms and visually inspect and mark crack locations on regular basis. Operations currently keeping equipment away from toe and inspecting while active in pit.  
View of east side of pit.
- Station 8:* Bell dump – swampy area contained by dump. Notice back tilting trees indicating local toe shearing in foundation. Dump on essentially flat ground. Important to dump and doze and limit crest advance rate to allow dissipation of pore pressures.
- Station 9:* Photo of east wall from north haulroad and photo of west wall.
- Station 10:* Photo of fault on southwest wall dipping at approximately 45°. Need to maintain keepout at toe when mining not active.  
Photo of northeast wall. Notice talus material above haulroad.
- Station 11:* Photo of east wall of Bell Pit. Notice raveled material above haulroad. Indicated that toppling is mechanism of instability. Golder has issued remedial design.  
Photo of west wall.
- Station 12:* Construction of foundation for heap leach site. Art Frye reported that verbal approval was provided by Chris Carr. Only seven metres deep and small trial. Permit application to follow.
- Station 13:* Northeast Zone Dump. Golder till design slightly steeper than if waste rock (no boulders in till to roll), but MPMC using the 20° rule to limit the potential for boulder roll-out.
- Station 14:* Photo of west wall of Wight Pit.
- Benches appear to be scaled adequately with shovel bucket.
  - Crest stakes in place on bench above shovel operating at 960m Level.
  - Local breakback and loss of bench crests.
  - Change to i-kon electronic detonators is indicated to have improved wall conditions.
  - Inspect crest on regular basis; visual monitoring; install prisms for baseline.
  - Golder doing quarterly inspections.
  - Blasting – no longer stemming back row of trim and buffer. Orica to recommend blast designs.
- Station 15:* Photo of pit bottom. Notice till slope in area of lower ramp. One more bench to go at pit bottom, then final cut will continue down.
- Station 16:* Photo of west wall. Local narrow catchment, but wall adequately scaled and no signs of rockfall at working level.
- Station 17:* Entrance to TSF haulroad. Much improvement since last inspection.
- Station 18:* Photo of NE dump looking north. Toe stakes are used to maintain overall slopes less than 20°. Notice portion overbuilt above road – no stability concerns noted.

### Close-out Meeting

Attendees: Tim Fisch, Art Frye, Bruce Milligan (MEMPR District Inspector).

### Tailings Storage Facility

- Inclinator shall be read with inclinometer probe during construction. Geotechnical consultant to specify frequency of readings.
- Minimum operating beach width to be specified by design consultant.
- Dam safety review in 2006.

### Bell Pit

- Daily prism monitoring and assessment of monitoring data on west and east wall instability areas in the Bell Pit.
- Manual wireline extensometer and manual crack monitoring devices (e.g., rebar pins) could be used for manual monitoring in addition to prism surveys.
- A suitably sized rockfall impact barrier shall be placed on the north haulroad below the area of active instability if raveling or rockfall hazards develop on the haulroad
- Threshold monitoring movement rate and operational response criteria shall be developed for the west and east walls of the Bell Pit and submitted to the Ministry within 15 days of the receipt of this report.
- The recommendations made by the design consultant for remedial design changes shall be followed.

### Bell North Dump

- Active dumping on the Bell North Dump is occurring on relatively flat ground, but in marsh materials.
- Tilting trees at the toe of the dump indicates that some shearing may be occurring in the foundation, at the toe of the dump. Crest advance rates shall be controlled to allow pore pressures to dissipate.
- Mount Polley's Standard Dump Procedure, dated February 16, 2006 shall be followed. If unusual cracking, settlements overhangs or toe movement has occurred, the pit supervisor shall decide to dump extra short and push, or block off the area and re-assign the trucks to other dump or stockpile areas. The supervisor shall follow the Mine Operations Dump Monitor procedures, dated February 16, 2006, if potential dump instability is observed.
- The inactive northern portion of the Bell North Dump shall be blocked off and limited to light vehicle access only while not in use.

### Northeast Zone Dump

- Operation of the East Rock Disposal Site (RDS) and TSF Haulage Road shall follow the M200 permit and variance conditions variance granted by the Chief Inspector. No geotechnical concerns were noted with respect to the Northeast Zone Dump.

### Wight Pit

- Structural breakback of bench crests noticed in upper benches, but recent change to i-kon electronic detonators is understood to be improving wall conditions.
- Walls look generally well scaled with shovel bucket during excavation.
- Prism monitoring shall be implemented starting with baseline prisms at the pit crest.
- Visual inspection of the pit crest shall be conducted on a regular basis.



Five Corners

Perimeter Seepage Pond

Perimeter Embankment

Barge

Main Embankment

Borr

South Embankment

Main Seepage Pond

FIG. 1

MT. POLLEY INSPECTION

AUG. 23, 2006

N. ROSE & TEAM MEMPH.



Aug 30/06

# BELL PIT - WEEKLY PLAN

AUG 23 - 29, 2006


~ 50 000 T  
@ 0.27 % CU  
& 0.27 G/T AU

~ 15,000 T  
@ 0.19 % CU  
& 0.24 G/T AU

## LEGEND

- Drill Pattern
- Waste Material
- △ Drilled Holes


FIG. 2  
MT. POLLEY  
AUG 30/2006



Aug 30/06

IRONMENTAL DITCH AND SUMP  
DO NOT DISTURB!!

WIGHT PIT - WEEKLY PLAN  
AUG 23 - 29, 2006



Till Contac


**LEGEND**

- Ore
- Drill Pattern
- Blasted Material
- Caved Holes

FIG. 3  
MT POLLEY  
AUG 30/06




FIG. 4  
Aug 30/06  
Mt Polley  
Geotechnical  
Inspection







△ photo 3904



△ photo 3917






Δ2 Photos 3905-09






Δ3 Photos 3910-16



Δ4 Photos 3918-21





AS Photos 3923-28





△5 Photo 3922



△6 Photo 3929





△6 photo 3930



△7 photo 3938





Δ7 Photos 3931-37





Δ7 Photo 3939



Δ8 Photo 3940





△8 Photo 3941



△8 Photo 3942





△9 Photo 3943-44





△9 Photo 3945-46





Δ10 Photo 3947

fault



Δ10 Photo 3948





Bill Photos 394g-50





11 Photos 3951-53





Δ12 Photo 3954



Δ13 Photo 3955





△13 Photo 3956



△16 Photo 3967





14 Photos 3957-63





Δ15 Photos 3964-66





△16 Photo 3968



△17 Photo 3969





D18 Photos 3970-71



Aug 30/06

## Mt Polley Geotechnical Inspection

Don Fish - Gen Mgr  
Art Frye - Manager of Oper.

- Northeast Zone Dump - check monitoring
  - extensometers

### Notes prior to inspection

- TSF - inclinometer to be used during construction
  - Visual monitoring
  - no piezometer data - Sept/05 to April/06 - leads & readout box need to be fixed
  - thresholds for piezometers 924 to 924.8m el.
  - Mill site sump spillway to be repaired
- \* - beach requirements?
  - monitoring as per frequency in ans -
  - tailings deposition plan - discharge piezometer, Mark & South Embankment
    - tailings pipeline extend to South Embankment
  - Relocate redoubt boxes
  - Review condition of existing pipeline - complete design review to ensure transport around entire TSF
  - Southeast ditch on West side of TSF needs to be relocated to higher ground
  - review water Management plan

### Southeast Zone Pit (not being mined yet & small)

- pit slope monitoring manual to be submitted to Chief Inspector within 6 months
- pit wall mapping - design updated annually - regular stability performance investigations & qualified geotech. eng.
- Dumps - submit plan & sections of East Waste Rock Dump to District & Geotechnical Inspector for approval.
- Dump operating manual.

Wright Pit - report on overburden soils

• geotechnical review

Met with Don Fish & Art Frye 9:30-10am

Tour of Tailings Dam with Ron Martel

Δ1 Mill site sump - rip rap required - erosion - needs remediation  
Stage 5 & 6 LHM - 20047 7 million - 4m DAB face

Jim McDonald & GRC Coffin - KP representatives on 4 in 4 out

Δ2 TSF from West barge

finer with berm - 2m minimum liner - test pits - backfill with berms  
- bathymetric survey  
- till core to GSC this year

Bob McGowan

- water balance → need to be @ 950.4 after spring runoff

- 1.35 total core

Δ3 Filter @ 947

Till Core 940.2

U Zone

Plots from Perimeter & Main embankments - where well developed bank  
- Brown till - & Grey till - winter.

- need single lane signage

Δ4 Inclinator #3 near toe of Main embankment - newly installed 41m depth  
pinned into bedrock

Δ5 TOC drain house - monitored weekly - photo of pond & downstream toe

- KP lightened up on inclinometer reading frequency - were using  
poor-boy probes - Permit requires inclinometer

- MPMC having difficulty acquiring  
probe - don't want to buy for one year  
studies.

KP representative

Jim McDonald - Les Galbraith - mid July

Ken Brower - mid Aug.

Matthew Silbermeyer - project coordinator ~~for~~ MPMC

- no indicated issues with specifications.

Δ5 Photo from Perimeter Embankment - where team placed to keep gradient  
on pipeline.

Δ6 Steel pipe for sewage water - to be connected in end of perimeter  
per pipe in embankment.

### Meeting with Art Frye 11:45 am

• mire plan -

- Wright pit fill - Southeast - 2:1 fill or reinforced wall.
  - upper 2:1 down to 40m within lake level.
  - working on final design Art Frye
  - looking at possibly going closer to Lake
  - 40m from Forestry - setback
  - old rotten cedars - tendency to fall down.
  - ramp has to be dropped 20m.

Wells - 15hp north  
30hp south

4 wells - 100 b.g. -

- 7hp to be installed

- piezometers to go in

- down to bedrock interface


- possibly up to 35m below lake level.

Ron Meisner - test pits

Aug 30/06

- Bell Pit - crack on west wall
- toppling on east wall -
- $42^\circ$  crest to fore - step out
- was  $51^\circ \rightarrow$  went to  $44^\circ$  1st

12m style  
70/72 - Bm berm  
44.1/45.2



- prism on west & east crests  
- 45° fault on west.

Pit/Dumps 12:50 pm

- $\Delta 7$  West wall crack - opened up 15cm - place pins for visual monitoring  
 - map cracks & place on plan.  
 View of east wall movement area on east wall  
 - west wall - continue to monitor & visually inspect - make notes on regular basis  
 - pins being ~~not~~ monitored daily - plotting  
 - open area - visually inspecting & keeping equipment away from toe
- $\Delta 8$  Bell Dump - contain swampy area - where trees tilting back near toe -  
 - essentially flat ground  
 - overbank dumping with dense vegetation.
- $\Delta 9$  NE Bell looking south - instability on east - having considered to have affected
- $\Delta 10$  Fault on south wall -
- $\Delta 11$  MM wall - where road material ravelled above slope  
 East wall Bell pit - Block lagging above ramp - bolder issued remedial recommendations in report.  
 - if raveling / rockfall develops reaching land out - may need impact beam
- $\Delta 12$  Preparation for heap leach - verbal approval from Chris Carr  
 7m deep
- $\Delta 13$  NE cone Dump - fill on NE - bolder design slightly steeper, but (no roll out)  
 MPMC using 200 rule for development
- $\Delta 14$  Photo of West wall of West pit - looks like benches being sealed adequately with bucket - change to Jims indicated to have improved wall conditions  
 - crest stakes on bench above shelter area  
 opening on 90m bench  
 - local breakback & loss of bench width  
 - inspect crest on regular basis - visual monitoring - pins.  
 - bolder doing quarterly inspections - monitoring recommended when needed  
 - no longer stemming back row - ORLA to recommend blast designs.
- $\Delta 15$  Till on SE of pit bottom - temporary wall - over mined at top - undermined @ bottom  
 - one more bench, then take down


Aug 30/06  
With Poldy

- ① 16 West wall - local narrow catchment, but wall adequately sized
- ① 17 - TSE road - road built up - road across go around & above
- ① 18 Photo of NE dump looking north - toe stakes placed on the left below  
notre portion overbuilt above road - waste rock - doesn't appear to be common.

### Close-out

- TSE - inclinometers read with probe during construction - not just post bag  
- dam safety review
- Bell Pit - monitor west & east walls - extensometers across cracks would provide  
monitored monitoring - pits  
- crest wall - if raveling persists - may need instrument them
- Wright Pit - adequate ditch berm  
- blasting
- NE dings - follow procedures
- beach with distribution from KP.
- Golder report provided - West & east wall instability.
- extensometers - across cracks - mark cracks  
- banner on ramp if raveling continues.
- Wright Pit - probes behind crest - baseline  
- berms - sealing with cut & chest - discuss with H. Chance.  
- inspection reports from Golder  
- best performance & bench performance
- threshold response criteria.

27151 Mt Rolley \ Aug 30/06 Photos




IM003904




IM003905



IM003906



IM003907



IM003908

3905-09



IM003909



IM003910



IM003911




IM003912



IM003913

3910-16




IM003914



IM003915



IM003916



IM003917



IM003918


3918-24



IM003919



IM003920



IM003921



IM003922




IM003923


3923-28




IM003924




IM003925




IM003926




IM003927



IM003928



IM003929



IM003930



IM003931



IM003932



IM003933

3931-37




IM003934




IM003935



IM003936



IM003937



IM003938





IM003939



IM003940



IM003941



IM003942



IM003943

\$ 1-3943-44 ✓



IM003944




IM003945



IM003946



IM003947



IM003948

3945-46 ✓



IM003949



IM003950



IM003951



IM003952



IM003953

1-3949-50 ✓ 3951-53 ✓




IM003954



IM003955



IM003956




IM003957



IM003958


3957-63 ✓



IM003959




IM003960




IM003961




IM003962



IM003963




IM003964



IM003965



IM003966




IM003967




IM003968


3964-66 ✓



IM003969



IM003970



IM003971

3970-71 ✓