

From: Les Galbraith
Sent: Wednesday, April 19, 2006 8:22 AM
To: Amanda Strouth
Subject: Piezometers

Amanda:

The piezometers on the ME will have to be relocated. This includes the piezometers that are currently located on the d/s toe of the existing shell zone as they will be buried when the Zone C is placed. A good place to locate the readout boxes is d/s of the ultimate toe in a place where they are unlikely to get damaged. This may require extra cable on a few of the piezos.

Call me if you have any questions regarding this.

Les Galbraith, P.Eng.
Senior Engineer

Knight Piésold Ltd.
1400 - 750 West Pender
Vancouver, B.C.
Canada V6C 2T8
Phone: +1 604 685 0543
Fax: +1 604 685 0147

<http://www.knightpiesold.com> (new web site)

This communication, including any attachments, is intended only for the use of the intended recipient(s) and is confidential. If the reader of this communication is not the intended recipient, any dissemination, distribution or copying of this communication is strictly prohibited. Knight Piésold does not warrant the accuracy of this communication. If you receive this communication in error, please notify the sender by return e-mail and delete this communication from your system.