



Province of British Columbia
Ministry of Energy, Mines and Petroleum Resources

MP00157

Report of Inspector of Mines
(Issued pursuant to Section 15 of the Mines Act)

File: 18040-02-07/MTPO/01

Geotechnical Inspection

NAME OF MINE:	Mt. Polley	LOCALITY:	
OWNER OR OPERATOR:	Imperial Metals Corp.	ADDRESS:	Suite 700 - 815 West Hastings St. Vancouver V6C 1B4
MANAGER:	Malcom Swallow	AREAS INSPECTED:	As noted

Persons Contacted

MANAGEMENT: J. Stevenson, E. Leneve
OHS COMMITTEE: N/A
WORKERS: N/A

MINISTRY OF ENERGY, MINES
AND PETROLEUM RESOURCES
REC'D NOV - 2 1995
MINE REVIEW AND PERMITTING

A copy has been forwarded to the Joint Occupational Health and Safety Committee and the union. The mine manager shall complete the right hand column noting specific corrective actions taken, or to be taken by a specified date, and return a copy to the Inspector within 15 days of receiving the report. Further, the manager shall post a copy to the bulletin board, to be replaced by a copy showing the manager's response. In this document, Code means Health, Safety and Reclamation Code for Mines in British Columbia.

INSPECTION REPORT	MANAGER'S RESPONSE OF ACTION TAKEN
<p>The inspection was conducted with J. Stevenson on October 11 and C. O. Brawner on October 19, 1995.</p> <p><u>Tailings Pond</u></p> <p>The inspections included review of surface and ground water conditions, soil conditions in test pits and surface drainage trenches and sediment control system. Test pit logs, photos and site plan provided by Knight Piesold were used during the second visit. The information was to assist in design review. Additional test pits to define permeable and / or soft foundation soils will be required as discussed with Knight Piesold.</p> <p>The sediment control post silt fence was discussed on the first inspection. It required additional filter cloth installation.</p>	<p>Noted.</p>

Copies To: B. McBride, J. Michell, W. Price

George S. Headley, M.Eng., P.Eng.
Senior Geotechnical Engineer

4th Floor, 1810 Blanshard St., Victoria, BC V8V 1X4
Address

Signature - Inspector

Signature - Manager

Date of Inspection: October 11 and 19, 1995

Dated: October 24, 1995