

From: Mark Burke
Sent: Friday, March 24, 2006 9:13 AM
To: Les Galbraith
Subject: Wight Pit road photos
Attachments: IMGA0121.JPG; IMGA0118.JPG; IMGA0113.JPG

Les,

I took some photos yesterday. Today is the first day of rain since i have been on site and the mud problem is much worse now. As you can see in the photo, there is several inches of mud covering the entire wight pit road. The mud flows down the road and pools on top of a creek gully, then it flows through the road and in to the lake. They are trying to ditch the water into the Wight pit so that it will not pool above the creek.

Mark