

Eric:

Attached is a figure showing foundation drain 5 from the main embankment. The approximate coordinates of the western extension of the drain are shown on the attached figure. I do not know how much fill is on top of the drain at this point. Please check this location with Mat on site to see if it might be possible to expose the drain and extend it around to the south embankment to convey the seep to the ME seepage collection pond.

Les Galbraith, P.Eng.
Senior Engineer

*Knight Piésold Ltd.
1400 - 750 West Pender
Vancouver, B.C.
Canada V6C 2T8
Phone: U' 604 685 0543
Fax: U' 604 685 0147*

<http://www.knightpiesold.com/> (new web site)

This communication, including any attachments, is intended only for the use of the intended recipient(s) and is confidential. If the reader of this communication is not the intended recipient, any dissemination, distribution or copying of this communication is strictly prohibited. Knight Piésold does not warrant the accuracy of this communication. If you receive this communication in error, please notify the sender by return e-mail and delete this communication from your system.