



MOUNT POLLEY MINING CORPORATION

A DIVISION OF IMPERIAL METALS CORPORATION

July 21, 1997

14745-40/MTR0/01

Province of British Columbia
Ministry of Employment and Investment
Energy and Minerals Division
4th Floor
1810 Blanchard St.
Victoria, BC V8W 9N3

Attention: George S. Headley P. ENG.


Dear Sirs:

Regarding your inspection of May 27, 1997 in reference to the South East Sediment Pond:

The soil spoil below the embankment toe is presently too soft to place a dozer on top. We will, therefore, bring in a Cat 215 excavator to slope the ditches and install drainage.

Sincerely,

Mount Polley Mining Corporation


George H. Wight
(General Manager)

MINISTRY OF EMPLOYMENT
AND INVESTMENT
REC'D JUL 29 1997

Cc: D. Pow (Prince George)

Don Parsons



Noted on bk #

Knicht Piésold Ltd.

CONSULTING ENGINEERS

Project: MT. POLLEY SE SEDIMENT POND
 Calculations for: KJB-KDE
 Calculations by: PETER PROCTER
 Checked by: WE Date: 14-Feb-97

Project No.: 1627
 Date: FEB 19/97
 Sheet 1 of 1



NOTE:
 1) All excavation cuts, fill /o/g, o/g and final fill surfaces surveyed by Ledcor. "As-built" of repaired areas to be completed by Ledcor.

FIGURE 1
NTS