

Photographs of Damaged Vane Blades

14-02091: Photos of the vane blade used for VST14-03 after depth 6.93m.



14-02091: Photos of the vane blade used for VST14-03 after consecutive tests at depths 12.2m, 12.5m, 12.8m and 13.13m.



14-02091: Photos of the vane blade used for VST14-10 after consecutive tests at depths 11.78m and 12.08m.

