




Job Number: 14-02091  
Client: Mount Polley  
Project: Mount Polley Mine, Likely, BC  
Sounding: VST14-03  
Sounding Date: 09-Oct-2014 14:38

Test Depth (m): 6.93  
Test Elevation (m): 925.84  
Vane Type: Rectangular 55 x 110 mm

Coordinate System: UTM North (NAD83)  
Northing (m): 5819931  
Easting (m): 595123  
Elevation (m): 932.77

### Vane Shear Test






Job Number: 14-02091  
Client: Mount Polley  
Project: Mount Polley Mine, Likely, BC  
Sounding: VST14-03  
Sounding Date: 09-Oct-2014 16:23

Test Depth (m): 12.20  
Test Elevation (m): 920.57  
Vane Type: Rectangular 55 x 110 mm

Coordinate System: UTM North (NAD83)  
Northing (m): 5819931  
Easting (m): 595123  
Elevation (m): 932.77

### Vane Shear Test






Job Number: 14-02091  
Client: Mount Polley  
Project: Mount Polley Mine, Likely, BC  
Sounding: VST14-03  
Sounding Date: 09-Oct-2014 16:23

Test Depth (m): 12.50  
Test Elevation (m): 920.27  
Vane Type: Rectangular 55 x 110 mm

Coordinate System: UTM North (NAD83)  
Northing (m): 5819931  
Easting (m): 595123  
Elevation (m): 932.77

### Vane Shear Test






Job Number: 14-02091  
Client: Mount Polley  
Project: Mount Polley Mine, Likely, BC  
Sounding: VST14-03  
Sounding Date: 09-Oct-2014 16:23

Test Depth (m): 12.80  
Test Elevation (m): 919.97  
Vane Type: Rectangular 55 x 110 mm

Coordinate System: UTM North (NAD83)  
Northing (m): 5819931  
Easting (m): 595123  
Elevation (m): 932.77

### Vane Shear Test





Job Number: 14-02091  
Client: Mount Polley  
Project: Mount Polley Mine, Likely, BC  
Sounding: VST14-03  
Sounding Date: 09-Oct-2014 16:23

Test Depth (m): 13.13  
Test Elevation (m): 919.64  
Vane Type: Rectangular 55 x 110 mm

Coordinate System: UTM North (NAD83)  
Northing (m): 5819931  
Easting (m): 595123  
Elevation (m): 932.77

### Vane Shear Test

