




Job Number: 14-02091
Client: Mount Polley
Project: Mount Polley Mine, Likely, BC
Sounding: VST14-10
Sounding Date: 20-Oct-2014 12:08

Test Depth (m): 11.48
Test Elevation (m): 920.60
Vane Type: Rectangular 55 x 110 mm

Coordinate System: UTM North (NAD83)
Northing (m): 5819961
Easting (m): 595151
Elevation (m): 932.08

Vane Shear Test






Job Number: 14-02091
Client: Mount Polley
Project: Mount Polley Mine, Likely, BC
Sounding: VST14-10
Sounding Date: 20-Oct-2014 13:01

Test Depth (m): 11.78
Test Elevation (m): 920.30
Vane Type: Rectangular 55 x 110 mm

Coordinate System: UTM North (NAD83)
Northing (m): 5819961
Easting (m): 595151
Elevation (m): 932.08

Vane Shear Test





Job Number: 14-02091
Client: Mount Polley
Project: Mount Polley Mine, Likely, BC
Sounding: VST14-10
Sounding Date: 20-Oct-2014 13:01

Test Depth (m): 12.08
Test Elevation (m): 920 .00
Vane Type: Rectangular 55 x 110 mm

Coordinate System: UTM North (NAD83)
Northing (m): 5819961
Easting (m): 595151
Elevation (m): 932.08

Vane Shear Test

