


Independent Expert Engineering Investigation and Review Panel

**Report on Mount Polley
Tailings Storage Facility Breach**

Appendix G: DRAWINGS

Drawing G1: TSF Crest and Pond Elevations

Mount Polley TSF Filling Curve



— Pond elevation - Sep 1996 to Jul 2010 - digitized from KP 2010 Annual Inspection Report, MP00037, Fig A1.1
 - · - Pond elevation - May 2010 to Nov 2013 - digitized from AMEC, MP00044, Fig 2.2
 - - - Pond elevation - Aug 2013 to Aug 2014 - from MPMC Daily Reports, MP10020
 — Embankment elevation at breach area - Jul 1996 to Sep 2010 - digitized from KP, MP00037, Fig A1.1
 - - - Embankment elevation at breach area - Mar 2010 to Aug 2014 - from AMEC and MPMC daily & weekly construction reports

TSF CREST AND POND ELEVATIONS

MOUNT POLLEY INDEPENDENT EXPERT ENGINEERING INVESTIGATION AND REVIEW PANEL

DESIGNED P JW	DRAWN N A K
APPROVED D. VAN ZYL	
DATE JANUARY 09, 2015	DWG. No. G1