
Independent Expert Engineering Investigation and Review Panel

Report on Mount Polley Tailings Storage Facility Breach

Appendix H: DRAWINGS

Drawing H1: Basis for Geometry Used for Stability Analysis

Drawing H2: Toe Geometry ComparisonDrawing H3: Water Table Variation



BASIS FOR GEOMETRY USED FOR STABILITY ANALYSIS

MOUNT POLLEY INDEPENDENT EXPERT ENGINEERING INVESTIGATION AND REVIEW PANEL

PJW NAK

APPROVED

N. MORGENSTERN

DATE

DECEMBER 16, 2014

DRAWN

NAK


APPROVED


DATE

DECEMBER 16, 2014

DWG. No.

H1





 PIEZOMETER G1-PE1-01 STOPPED READING IN 2002 & G03 STOPPED READING IN MAY 2014.

WATER TABLE VARIATION

PJW NAK

APPROVED

N. MORGENSTERN

DATE

DWG. No.

MOUNT POLLEY INDEPENDENT EXPERT ENGINEERING INVESTIGATION AND REVIEW PANEL DECEMBER 16, 2014

110